

COMO 3 CORETCIONX COLUMNINCTURECKUX PECTYGRINK

(a) SU(a) 1686124 A1

(51)5 E 21 B 29/10

ГОСУДАРСТВЕННЫЙ КОМИТЕТ NO NACEPETEHNAM IN OTKPLITHAM DEM FINT CCCP

ОПИСАНИЕ ИЗОБРЕТЕНИЯ

К АВТОРСКОМУ СВИДЕТЕЛЬСТВУ

(21) 4678841/03

(22) 24.02.89

(45) 23.10.91. 5юл. № 39

(71) Всесоюзный научно-исследовательский и проектный институт по креплению скважин и буровым растворам

(72) О.А. Ледяшов, С.Ф. Петров, М.Л. Кисельман, В.И. Мишин и А.В. Бреус

(53) 622.245.4(088.8)

(56) Авторское свидетельство СССР Nº 976019, KA. E 21 B 29/10, 1982.

Нефтяное хозяяство. 1987, № 2, с. 76-

(54) СПОСОБ РЕМОНТА ОБСАДНОЙ КО-**ЛОННЫ**

(57) Изобретение относится к ремонту обсадных колони эксплуатационных, нагнетательных и других схважин. Целью изобретения является повышение эффективности ремонта обсадной колонны за счет увеличения устойчивости пластырей действию сминающих усилий при депрессиях. превышающих 8-9 МПа. Для этого после установки в месте дефекта первого продольно гофрированного пластыря устанавливают второй. Причем периметр второго пластыря выбирают маньшим периметра первого пластыря, а периметр первого выбирают меньшим париметра обсядноя колониы. Длину второго устанавливаемого пластыря выбирают большей длины первого на величину, большую рабочего хода гидравлической дорнирующей головки. Перед установкой второго пластыря один из его торцов смещают относительно торца первого на величину рабочего хода гидравлической дориирующей головки в направлении, противоположном направлению рабочего хода дорнирующей головки.

2 -

Изобретение относится к ремонту эксплуатационных, нагнетательных и других скважим, более точно к восстановлению герметичности обсадных колони металлическими пластырями.

Целью изобретения является повышение эффективности ремонта обсадной колонны за счет увеличения устойчивости пластырей действию сминающих усилий при депрессиях, превышающих 8-9 МПа.

Способ осуществляется следующим об-

В скважину спускают первый продольно гофрированный пластырь периметром, большим периметра обсадной колонны, доставляют его к месту дефекта обсадной ко-

вонны и устанавливают в этом месте прижатием гидравлической дорнирующей головки. Затем к месту дефекта спускают второй продольно гофрированный пластырь периметром, меньшим периметра первого устанавливаемого пластыря, и длиной, большей длины первого устанавливаемого пластыря, на величину, большую рабочего хода гидравлической дорнирующей головки. Перед установкой второго пластыря один из его торцов смещают относительно торца первого пластыря на величину рабочего хода гидравлической дорнирующей головки в направлении, противоположном направлению рабочего хода гидравлической дорнирующей головки, в затем производят установку второго пластыря внахлест с первым и полным перекрытием первого патрубка по всей его длине.

Опыт свидетельствует, что при ремонте 5 колонн 140, 146, 168 и 178 мм при получении точной информации о действительном периметре внутренией поверхности колоним (показания измерителя периметра, измерения при спуске труб в скважину для экспа- 10 римента) оптимальным является натяг в 1 мм по дивнетру или 3 мм по периметру, то есть Пр-Панд.+3. В этом случае осевое усилие и девление в цилиндре дорна при установке пластыря находятся в рекомендуеных 15 пределях, достигается надежная герметичность.

При использовании производственной информации о толщине стенки трубы в ин- 20 тервале ремонта рекомендуется принимать П:-Пыс.+6.

Большинство труб согласно многочислениым замерам имеют действительные приблизительно на 1 мм больше номинальных значений, что находится в пределах и в соответствии с допусками по ГОСТу. Кроме того, работа с фактическим натягом в пределах +6 ым вполне привилема и не вызывает 30 превышения допустимых нагрузок.

После установки первого пластыра внутренний диаметр dan и периметр П_{ви} сортаетствению составляют

$$d_{\text{sut}} = d_{\text{su.x}} - 2 \partial = d_{\text{su.x}} - 6$$
;
 $\Pi_{\text{sut}} = \pi (d_{\text{su.x}} - 2 \partial) = \Pi_{\text{su.x}} - 18$.

Считая, что сведения о был и Пыл. также опираются на производственную документацию (dank и Попк), для участка двойного перекрытия согявсно методике кэншена отзывид йынтнельвияхс тогородив поверхности оз и периметр Пз второго пластыря

$$d_2 = d_{BH1} + 2 = d_{BH,E} - 6 + 2 = d_{BH,E} - 4;$$
 $\Pi_2 = \Pi_{BH1} + 6 = \Pi_{BH,E} - 18 - 6 = \Pi_{BH,E} - 12.$

Таким образом, при выборе первого и второго пластырей рекомендуется прини-: 12 ть П = П_{вых.} + 6 и П2 = П_{вых} — 12 (при ∂ = 3).

В значении П2 могут быть энесены коррективы по результатам установки первого пластыря. Если усилие на дорнирующей головке при его расширении окажется значительно ниже нормального (14-18 т) - признак того, что деяствительное Пылк больше, 55 Пу следует выбрать увеличенным на 2-5 мм соразмерно степени уменьшения действительной осевой силы, если усилие окажется выше нормы. П2 следует уженьшить соответствующим образом.

Таким образом, к неравенству П1> >Пен.к > П2 уместны следующие дополне-

 $\Pi_1 = \Pi_{\text{aug}} + 6$; $\Pi_2 = \Pi_{\text{aug}} - 12 \pm (2 - 5)$.

Длину первого пластыря выбирают так, чтобы перекрыть дефект с достаточным перехлестом вверх и вниз (+1,5-2,5 м). Величину перехлеста следует выбирать в указакных пределах, увеличивая или уменьшая его в зависимости от степени достоверности информации о размере и месте дефекта. Длина второго пластыря прежде всего должна соответствовать с запасом длине дефектной чести колонны и перекрывать соответствующий участок первого пластыря.

Считая, что первый пластырь установлен в требуемом месте и обеспечено заданное перекрытие дефекта с перехлестом по длине, при выборе размеров и схемы установки второго пластыря возможны следуюцые варианты. Технология установки пластыря включает три этапа: расширение начального участка для зацепления пластыря с обседной колонной путем втягивания довнешний и особенно внутренний диаметры 25 риирующей головки под давлением гидродомкратом на величкну его хода - 1,5 м при удержании пластыря от осевого смещения упором устройства: расширение основного участка пластыря протягиванием дорнируюшей головки (обычно без давления) талевой системой, пластырь при этом разгружается от осевого воздействия головки через начальный расширенный участок на колонну: запрессовка расширенного пластыря мно-35 гократиым проходом дорнирующей головки под давлением.

Опасность смещения пластыря по колонне возникает на втором этапе установки -ональмы виновлюрь соонроть тоодон вс-си го расширенного участка, например при значительном несоответствии натягов. При недостаточном или отынцательном натяга изчальный участок после расширения может быть недостаточно прижат к колоние. 45. При большом избыточном натяге гидродомкрат при заданном давлении может втянуть головку в пластырь на незначительную VACTA CROSTO XODS.

Второй пластырь выполняется с пери-50 метром согласно рекомендации, длина принимается в соответствии с длиной первого пластыря плюс 1,5-2,0 м. При спуске нижний конец располагают на 1.5-2.0 м ниже торца первого пявстыря. Далее – расширенив начального участка с разгрузкой верхнего торца пластыря в упор дорна, затем протягивание дорнирующей головки без дваления - расширение основной части и запрессовка пластыря в несколько проходов дорнирующей головки под давлением 120-150 Kr/CM²

Таким образом достигается гарантированное расширение начального участка на полный ход гидродомкрата, так как периметр второго пластыря на участке ниже торца первого на 12 мм меньше периметра обседной колонны Памл и расширение происходит при большом отрицательном натяга (по существу в безопорном режиме). При 10 последующим протягнавним доримрующая головки без давления пластырь либо удерживается за счет зацепления начального участка в колоние, либо смещается вверх до рвого пластыря. Упор обеспечен надежный, так как периметр расширенного участка второго пластыря на 6 мм (по диаметру на 2 мм) превышает внутреннюю поверхность первого пластыря

 $\Pi_2 - \Pi_{\text{sM},1} = \Pi_{\text{sM},K} - 12 - \Pi_{\text{sM},K} + 6 = 6.$

Расширенив основной части второго пластыря на всей ее длине производится дорнирующей головкой без давления, т.е. с исключает случайность. Пластырь гарантирован от смещения по колоние на величину, превышающую специально предусмотренное смещение, всегда точно размещается в соответствующем месте, полностью перекрыв дефект колонны.

формула изобретения

Способ ремонта обсадной колонны, включающий спуск к месту дефекта обсадной колонны двух продольно гофрированных пластырей и их последовательную установку внахлест и прижатие к обсадной колоние пидравлической дорнирующей головкой, отамчающийсятем, что, с целью повышения эффективности ремонта обсадной колониы за счет увеличения устойчивости пластырей действию сминающих силий при депрессиях, превышающих 8упора расширенным участком в торец пер- 15 9 МПа, периметр первого устанавливаемого пластыря выбирают больше периметра ремонтируемой обсадной колонны, периматр второго устанавливаемого пластыря выбирают меньшим периметра первого устанавливаемого пластыря, а длину второго устанавливаемого пластыря выбирают большей длине первого на величину, большую рабочего хода гидравлической доринрующей головки, причем перед установкой минимальным осевым усилием, что также 25 второго пластыря один из его торцов смещают относительно торца первого на величину рабочего хода гидравлической дорнирующей головки в направлении, противоположном направлению рабочего хода гидрав-30 лической дорнирующей головки.

> Составитель И.Левкоева Техред М.Моргентал

Корректор М.Денчик

Редактор И.Шулла

Тираж

Подписнов

3akas 3583 ВНИИПИ Государственного комитета по изобретениям и открытиям при ГКНТ СССР 113035, Москва, Ж-35, Раушская наб., 4/5

[state seal]

Union of Soviet Socialist Republics

Republics
USSR State Committee

on Inventions and Discoveries of the State Committee on Science and Technology (19) <u>SU</u> (11) <u>1686124 A1</u>

(51)5 E 21 B 29/10

SPECIFICATION OF INVENTOR'S CERTIFICATE

(21) 4679841/03

(22) Feb, 24 1989

(46) Oct, 23 1991, Bulletin No. 39

(71) All-Union Scientific-Research and Planning Institute of Well Casing and Drilling Muds

(72) O. A. Ledyashov, S. F. Petrov, M. L. Kisel'man, V. I. Mishin, and A. V. Breus (53) 622.245.4 (088.8)

(56) USSR Inventor's Certificate No. 976019, cl. E 21 B 29/10, 1982.

Neftyanoe Khozyaystvo, No. 2, pp. 76-78.

(54) A METHOD FOR CASING REPAIR

(57) The invention relates to repair of casings in development, injection, and other wells. The aim of the invention is to improve the effectiveness

of casing repair by increasing the collapse resistance of the patch for drawdowns exceeding 8-9 MPa. For this purpose, after placement of a first longitudinally corrugated patch at the location of the defect, a second patch is placed. Here the perimeter of the second patch is selected to be less than the perimeter of the first patch, while the perimeter of the first patch is selected to be less than the perimeter of the casing. The length of the second patch to be placed is selected to be greater than the length of the first patch by an amount greater than the working travel of the hydraulic coring head. Before placing the second patch, one of its ends is displaced relative to the end of the first patch by an amount equal to the working travel of the hydraulic coring head, in the direction opposite to the direction of working travel of the coring head.

[vertically along right margin]

(19) \underline{SU} (11) $\underline{16}$

(11) 1686124 A1

1686124

1

The invention relates to repair of development, injection, and other wells, more precisely to restoration of leaktightness of casings by means of metal patches.

The aim of the invention is to improve the effectiveness of casing repair by increasing the collapse resistance of the patch for drawdowns exceeding 8-9 MPa.

The method is carried out as follows.

A first longitudinally corrugated patch of perimeter greater than the perimeter of the casing is lowered into the well, it is conveyed to the location of the defect in the casing,

and is placed in this location by squeezing by the hydraulic coring head. Then a second longitudinally corrugated patch, with perimeter less than the perimeter of the patch to be placed first and a length greater than the length of the patch to be placed first by an amount greater than the working travel of the hydraulic coring head, is lowered to the location of the defect. Before placement of the second patch, one of its ends is displaced relative to the end of the first patch by an amount equal to the working travel of the hydraulic coring head, in the direction opposite to the direction of the working travel of the hydraulic coring head, and then

the second patch is placed to overlap the first patch and the first sleeve is completely covered over its entire length.

Experience shows that for repair of 140 mm, 146 mm, 168 mm, and 178 mm strings, if accurate information is obtained about the actual perimeter of the inner surface of the string (perimeter gage readings, measurements when lowering the pipes into the well for the experiment), the optimum allowance is 1 mm with respect to diameter or 3 mm with respect to perimeter, i.e., $P_1 = P_{\text{in.str}} + 3$. In this case, the axial stress and the pressure in the cylinder of the mandrel during placement of the patch is found to be within the recommended range, and reliable leaktightness is achieved.

When using manufacturer's information about the wall thickness of the pipe in the repair interval, it is recommended to assume that $P_1 = P_{in.str} + 6$.

Most pipes, according to many measurements, have actual outer and especially inner diameters approximately 1 mm greater than the nominal values, which is within the range and in conformance with GOST [State Standards] tolerances. Furthermore, work with an actual allowance in the range +6 mm is quite acceptable, and does not result in exceeding the permissible loads.

After placement of the first patch, the inner diameter d_{in} and the perimeter P_{in} are respectively

$$d_{in1} = d_{in.str.} - 2\delta = d_{in.str.} - 6;$$

 $P_{in1} = \pi(d_{in.str.} - 2\delta) = P_{in.str.} - 18.$

Assuming that the information about d_{in1} and P_{in1} also is based on the manufacturer's documentation ($d_{in.str.}$ and $P_{in.str.}$), for the section of double overlap according to the procedure, we select the equivalent diameter of the outer surface d_2 and the perimeter P_2 for the second patch

$$d_2 = d_{in1} + 2 = d_{in.str.} - 6 + 2 = d_{in.str.} - 4;$$

 $P_2 = P_{in1} + 6 = P_{in.str.} - 18 - 6 = P_{in.str.} - 12.$

Thus when selecting the first and second patches, it is recommended to use $P_1 = P_{in.str.} + 6$ and $P_2 = P_{in.str.} - 12$ (for $\delta = 3$).

Corrections may be made to the value of P₂ according to the results of placement of the first patch. If the force on the coring head during expansion of the first patch proves to be significantly lower than normal (14-18 tons), this is an indication that the actual P_{in.str.} is larger, and P₂ should be selected as 2-5 mm greater in proportion to the degree of decrease in the actual axial force; if the force proves to be higher than the normal value, P₂ should be decreased accordingly.

4

Thus it is appropriate to add the following to the inequality $P_1 > P_{in.str.} > P_2$:

$$P_1 = P_{in.str.} + 6$$
; $P_2 = P_{in.str.} - 12 \pm (2-5)$.

The length of the first patch is selected so that the defect is covered with sufficient overlap above and below (+1.5-2.5 m). The overlap should be selected within the indicated range, increasing or decreasing it depending on the extent to which the information about the size and location of the defect is reliable. The length of the second patch especially must correspond to a conservative estimate of the length of the defective portion of the string, and must overlap the corresponding portion of the first patch.

Assuming that the first patch is placed at the required location and that the specified coverage of the defect with overlap along the length is assured, in selecting the dimensions and configuration for placement of the second patch, the following embodiments are possible. The technology for placement of the patch includes three stages: expansion of the initial portion to make contact between the patch and the casing, by means of pulling in the coring head under pressure, using the hydraulic jack, by a distance equal to its travel, 1.5 m, while the patch is restrained from moving axially by the stop of the device; expansion of the main portion of the patch by pulling the coring head through (usually without pressure) by means of a block-and-tackle system, where the axial loading of the patch by the head is relieved through the initial expanded portion to the string; pressing of the expanded patch by multiple passes of the coring head under pressure.

A risk of the patch shifting along the string arises in the second stage of placement due to insufficient contact made by the initial expanded portion, for example when there is significant mismatch of the allowances. For insufficient or negative allowance, the initial portion after expansion may be insufficiently squeezed against the string. When the excess allowance is large, the hydraulic jack for the specified pressure may pull the head into the patch by a distance equal to an insignificant portion of its travel.

The second patch is made with a perimeter according to the recommendation, the length is taken to match the length of the first patch plus 1.5-2.0 m. When lowered, the lower end is positioned 1.5-2.0 m below the end of the first patch. Next: expansion of the initial portion with the stop of the mandrel relieving the load on the upper end of the patch, then pulling the coring head through without pressure; the expansion of the main portion and pressing of the patch in several passes

of the coring head under a pressure of 120-150 kg/cm².

Thus expansion of the initial portion for complete travel of the hydraulic jack is assured, since the perimeter of the second patch in the portion below the end of the first patch is 12 mm less than the perimeter of the casing P_{in.str.}, and expansion occurs with a large negative allowance (essentially under unsupported conditions). When the coring head is subsequently pulled through without pressure, the patch either is restrained because of contact made with the initial portion in the string, or is shifted upward as far as it will go by the expanded portion to the end of the first patch. Reliable seating is assured, since the perimeter of the expanded portion of the second patch is 6 mm greater (2 mm greater in diameter) than for the inner surface of the first patch

 $P_2 - P_{in1} = P_{in.str.} - 12 - P_{in.str.} + 6 = 6.$

Expansion of the main portion of the second patch over its entire length is carried out by the coring head without pressure, i.e., with minimal axial stress, which also eliminates accidents. The patch is guaranteed not to move along the string a distance greater than the specially called for displacement, and is always disposed precisely at

the appropriate location, and the defect in the string is completely sealed.

Claim

A method for repair of a casing, including lowering to the location of the defect in the casing of two longitudinally corrugated patches and their successive overlapping placement and squeezing against the casing by a hydraulic coring head, distinguished by the fact that, with the aim of improving the effectiveness of casing repair by increasing the collapse resistance of the patch for drawdowns exceeding 8-9 MPa, the perimeter of the first patch to be placed is selected to be greater than the perimeter of the casing under repair, the perimeter of the second patch to be placed is selected to be less than the perimeter of the first patch to be placed, and the length of the second patch to be placed is selected to be greater than the length of the first by an amount greater than the working travel of the hydraulic coring head, where before placement of the second patch, one of its ends is moved relative to the end of the first patch by a distance equal to the working travel of the hydraulic coring head, in the direction opposite to the direction of working travel of the hydraulic coring head.

Editor I. Shulla	Compiler I. Levkoeva Tech. Editor M. Morgental	Proofreader M. Demchik
Order 3583	Run	Subscription edition

All-Union Scientific Research Institute of Patent Information and Technical and Economic Research of the USSR State Committee on Inventions and Discoveries of the State Committee on Science and Technology [VNIIPI]

4/5 Raushkaya nab., Zh-35, Moscow 113035

"Patent" Printing Production Plant, Uzhgorod, 101 ul. Gagarina



AFFIDAVIT OF ACCURACY

I, Kim Stewart, hereby certify that the following is, to the best of my knowledge and belief, true and accurate translations performed by professional translators of the following patents/abstracts from Russian to English:

ATLANTA BOSTON BRUSSELS CHICAGO DALLAS FRANKFURT HOUSTON LONDON LOS ANGELES MINNEAPOLIS NEW YORK PHILADELPHIA SAN DIEGO SAN FRANCISCO SEATTLE.

WASHINGTON, DC

Patent 953172 Abstract 976020 Patent 1686124A1 Patent 1747673A1

Kim Stewart

TransPerfect Translations, Inc. 3600 One Houston Center

1221 McKinney

Houston, TX 77010

Sworn to before me this 14th day of February 2002.

Signature, Notary Public

OFFICIAL SEAL MARIA A. SERNA **VOTARY PUBLIC** 32 for the State of Texas revission expires 03-22-2009

Stamp, Notary Public

Harris County

Houston, TX

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
☐ GRAY SCALE DOCUMENTS
LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
OTHER:

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.